






INSTRUCTIONS

RLV-KS





013R9277

013R9277




G 3/4 A

30 - 40 Nm









G 1/2

10 mm



30 - 40 Nm



6 mm