



INSTRUCTIONS


VMT




065R9181

065R9181

<p>1</p> <p>DANFOSS A65G26.12</p>	<p>2</p> <p>DANFOSS A65F51.11</p>
<p>3</p> <p>DANFOSS A65F52.11</p>	<p>4</p> <p>DANFOSS A65F53.11</p> <p> $\phi 15, \phi 16: 1\frac{1}{4} \rightarrow 1\frac{1}{2}$ $\phi 15, \phi 16: 1 \rightarrow 1\frac{1}{4}$ $\phi 28: \frac{3}{4} \rightarrow 1$ </p>
<p>5</p> <p>DANFOSS A65F14.12</p>	<p>6</p> <p>DANFOSS A65F13.12</p>
<p>7</p> <p>DANFOSS A13L147.10</p>	<p>8</p> <p>DANFOSS A13L148.11</p>



9



Type	Max. Δp_v bar (lbf/in ²)					
	VMT-/2			VMT-/8		
	15	20	25	15	20	25
ABV-VMT	1.1 (17)	1.0 (15)	0.65 (10)	7 (105)	4.5 (68)	4.5 (68)
ABNV-VMT	—			0.8 (12)		
RAV-VMT	0.2 (3)			0.8 (12)		
RAVV/K/I-VMT	0.2 (3)			0.8 (12)		

10